

Gagemaker T057 | UN Series (60° V) Threads | Pitch 10



With 60° "V" thread forms, these contact points are used to inspect the pitch diameter of machined parts. For the majority of gauges, two are needed.

| Specifications | Details |
|----------------|---------|
| Pitch | 10 |

